



Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

September 16, 1988

Mr. Andy King
Genwal Coal Company
P. O. Box 1201
Huntington, Utah 84528

Andy
Dear Mr. King:

Re: Requirements for Sediment Ponds, Genwal Coal Company, Mohrland
Loadout, [REDACTED] Emery County, Utah

Division requirements relating to pond inspections, certifications, and as-builts are being scrutinized during federal inspections. I have asked Harold G. Sandbeck Reclamation Inspector, to review your Mohrland pond requirements with you, and to discuss completion of the requisite reports, where necessary.

If remedial action is required to bring the Mohrland pond into compliance with the regulations, you should take the requisite steps prior to the next state inspection. Thank you for your cooperation.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Lowell'.

Lowell P. Braxton
Administrator
Mineral Resource Development
and Reclamation Program

c1

cc: S. Linner
H. Sandbeck

WPOB28/4